



FIG. 1



**F I G. 2**

**FIG. 3**






FIG. 4



**F I G. 5**

6/23

**F I G. 6**




FIG. 7







FIG. 8



**F I G. 9A****F I G. 9B**

**F I G. 10**







FIG. 11




**FIG. 12**


**F I G. 13**




## FIG. 14




**FIG. 15**




**FIG. 16**





**FIG. 17**



**FIG. 18**



**F I G. 19**

**F I G. 20**

## FIG. 21

URL <http://www.maintain.co.jp/db/input.html>

TROUBLE DB INPUT WINDOW

DATE OF OCCURRENCE [2000/3/15] ~ 404

MODEL [\*\*\*\*\*] ~ 401

SUBJECT [OPERATION FAILURE (START-UP ERROR)] ~ 403

EQUIPMENT S/N [465NS4580001] ~ 402

URGENCY [D] ~ 405


SYMPTOM [LED KEEPS BLINKING  
AFTER POWER-ON]  
[Up/Down/Left/Right navigation buttons]

REMEDY [POWER ON AGAIN  
(PRESS RED BUTTON AT POWER-ON)]  
[Up/Down/Left/Right navigation buttons]

PROGRESS [TEMPORARY MEASURE  
HAS BEEN TAKEN]  
[Up/Down/Left/Right navigation buttons]

[SEND] 410 [RESET] 411 [ ] 412

LINK TO RESULT LIST DATABASE   SOFTWARE LIBRARY   OPERATION GUIDE

**F I G. 22**

FLOW CHART OF SEMICONDUCTOR DEVICE MANUFACTURING PROCESS

FIG. 23

